
Tuesday, 09/10/2007 2:55:16 PM User Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : ARM : 35031 -/ Job Number : 12883 **Estimate Number** : MA Part Number : D3560043 P.O. Number S.O. No. : P/A : D3560 REV C This Issue : 09/10/2007 **Drawing Number** : N/A Prsht Rev. Project Number : MA : SMALL/MED FAB : C First Issue Type **Drawing Revision** AIU: : 35031 Previous Run Material Each : 19/10/2007 Qty: **Due Date** Written By Checked & Approved By Comment : Est Rey:A New Issue 07.05.24 EC Est Rev B ECN 987 07.10.09 EC **Additional Product** Job Number: Seq. #: Machine Or Operation: Description: M6061T6B0500X05000 6061-T6 Bar .50" x 5.0" 1.0 Comment: Qty.: 1.3598 f(s)/Unit Total: 13.5975 f(s) 6061-T6 Bar 0.50" x 5.00" Batch: 3104598 156 BAND SAW 2.0 Comment: BAND SAW Cut blanks 15.500" long (10) 3.0 HAAS CNC VERTICAL MACHINING #1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA695 Rev: AA & Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE BG QC8 SECOND CHECK 5.0 Comment: SECOND CHECK



Tuesday, 09/10/2007 2:55:16 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Part Number: D3560043 Job Number: 35031 Job Number: Seq. #: Description: Machine Or Operation: PLATE D35921 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) PLATE LARGE FABRICATION RESOURCE 1 7.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (60) 8- on one side weld from bottom to top-half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) INSPECT WORK TO CURRENT STEP QC5 8.0 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 90 QC9 Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION



Tuesday, 09/10/2007 2:55:16 PM Date: User: Linda Lacelle **Process Sheet** Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Job Number: 35031 Part Number: D3560043 Job Number: Seq. #: Description: Machine Or Operation: 12.0 D2808 Spacer Comment: Qty.: Total: 10.0000 Each(s) 1.0000 Each(s)/Unit Spacer MF 07-12-03 batch: SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 13.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 7-12-03 1-Press bushing in D3560 arm per dwg D3562 INSPECT WORK TO CURRENT STEP 14.0 QC5 Comment: INSPEC WORK TO CURRENT STEP 15.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: ILA 16.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE 18.12.11 Job Completion

Page 3

Form: rprocess



Friday, 10/5/2007 10:58:42 AM ·Date User Kim Johnston **Process Sheet** : CU-DAR001 Dart Helicopters Services **Drawing Name** : ARM Customer Job Number : 12883 Estimate Number : D3560043 Part Number P.O. Number : D3560 UNDER REVIEW : 10/5/2007 S.O. No. : **Drawing Number** This Issue : NC Project Number : N/A Prsht Rev. * C : SMALL /MED FAB First Issue : 11 **Drawing Revision** Type : 34966 Material Previous Run Each Due Date : 10/19/2007 10 Um: Written By Checked & Approved By : Est Rev:A New Issue 07.05.24 Comment Additional Product Job Number: Machine Or Operation: Description: Seq. #: 6061-T6 Bar 50" x 5.0" 13.9975 f(s) Comment: Qty.: Total: 1.3598 f(s)/Unit 6061-T6 Bar 0.50" x 5.00" Batch: BAND SAW BAND SAW 20 Comment: BAND SAW Cut blanks 15.500" long HAAS CNC VERTICAL MACHINING #1 3.0 HAAS1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA695 Rev: _____ & Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 INSPECT PARTS AS THEY COME OFF MACHINE 4.0 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK 5.0 Comment: SECOND CHECK

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								24 To 100 To
Part No:		PAR #:	Fault Categ	gory:		No DQA:		
NCR:			WORK ORDE	R NON-CONFORMA				14 🖺
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval
DAIL		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
H.								
A.=								

NOTE: Date & initial all entries

Date: -Friday, 10/5/2007 10:58:42 AM .User: · Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35031 Part Number: D3560043 Job Number: Description: Seq. #: Machine Or Operation: D35921 PLATE 60 Comment: Qty.: 1.0000 Each(s)/Unit Total: 10.0000 Each(s) PLATE LARGE FAB 1 LARGE FABRICATION RESOURCE 1 70 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 QC5 INSPECT WORK TO CURRENT STEP 8.0 Comment: INSPEC WORK TO CURRENT STEP QC9 ISUAL WELDING INSPECTION 90 Comment: VISUAL WELDING INSPECTION HAND FINISHING RESOURCE #1 10.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 110 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING 1 PACKAGING RESOURCE #1 12.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: FINAL INSPECTIONW/O RELEASE 13.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Form: mrocess

Page 2

Dart Aerospace Ltd

Dart Ae	rospace L	_td							
V#/O:	400		WC	RK ORDER CHANGE	S				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву			Approval Chief Eng / Prod Mgr	Approval QC Inspector
1			98						
				- Rhan Helicip					1
					05 1				1
									1
				A STATE OF S					
Part No		PAR #:	Fault Cated	iory:	NCR: Yes	No DQ	A:	Date:	1
				THE STATE OF THE S				_ Date: _	
NCR:			WORK ORDE	R NON-CONFORMAL					
MOIN.						-,			120
DATE	STEP	Description of NC Section A	Initial	Corrective Action Section Action Description	Sign		cation on C	Approval Chief Eng	Approval
4		Sediotry	Chief Eng	Chief Eng	Date		on C	Chief Eng	QC Inspector
+	事事目					44			懂
į.								-	
	A TENER	### ### ### ### ### ### ### #### ######							
}									lit.
	26.15								
	THE COLUMN			TOTAL STREET, LINE					- 2
	148							5	1. 72

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	35031
Description: Arm	Part Number:	D3560-3
Inspection Dwg: D3560 Rev: 8		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.5065	~			
Ø0.196	+0.005/-0.001	-196	-			
Ø1.000	+0.010/-0.001	1-00-1	<u></u>			
Ø0.900	+0.010/ 0.001	.900				
0.500	+/-0.010	. ન ભવ				
0.250	+/-0.010	. 751	-			
0.275	+/-0.010	- 775				
0.188	+/-0.010	191				
2.000	+/-0.010	2005	V			
1.750	+/-0.010	1.755	~			
1.702	+/-0.010	1.707	~			
Ø0.385 x 100°	+/-0.010 x 0.5°	-380KK	_			
0.250 Deep	+/-0.010	12117	~			
						1-2
	×					

Measured by:	36	Audited by:	Jul	Prototype Approval:	N/A
Date:	07.10.28	Date:	07/10/28	Date:	N/A

	Rev	Date	Change	Revised by	Approved
	Α	07.01.17	New Issue P/o P3500-043	KJ/JLM 1.A	
1	В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM KJ/JLM	E
- 1				. (1)	




03560-1 ARM (-041, SHOWN) OR D3560-2 ARM (-042, OPPOSITE) D3592-1 PLATE, SEE DETAIL A

> D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)

D3560-3 ARM (-D43, SHOWN) OR D3560-4 ARM (-044, OPPOSITE) D3592-1 PLATE, -SEE DETAIL A

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)



GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH; CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	С	07.06.19	REMOVE POWDE	ER COAT
	В	07.01.15	REDESIGN AS V	WELDMENT, ADD POCKETS
	A	06.09.25	NEW ISSUE	
COPYTRIGHT @ 2008 BY DART AEROSPACE LITO.	DESIGN	OPAWN BY	DART	DART AEROSPACE LTD.
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKED	APPROVED #	DRAWING NO. D3560	REV. C SHEET 1 OF 3
OR COPIED OR COMMUNICATED TO ANY OTHER	DATE		TITLE	SCALE
DART AEROSPACE LTD.	07.06.19		ARM WELDMENT	314



